

Utah Department of Environmental Quality

Division of Drinking Water

Public Water System Inventory Report

Run Date:
08/04/2011 12:39 pm

PWS ID: UTAH22069 **Name:** CANYON RIM RANCH SUBDIVISION
Legal Contact: CANYON RIM RANCH SUBDIV **Rating:** Approved
DELRIE W GALE **Rating Date:** 04/09/1996
Address: 1090 N 3500 W **Activity Status:** Active
VERNAL, UT 84078
Phone Number: 435-789-8937
City Served (Area):
County: SUMMIT COUNTY
System Type: Non-community **Last Inv Update:** 07/18/2011 **Avg Daily Prod:**
Activity Status Cd: Active **Last Snty Srv Dt:** 11/07/2008 **Total Dsgn Cap:**
Population: 105 **Surveyor:** ROY DIXON **Total Emerg Cap:**
Oper Period: 5/1 to 9/30

Gal/Day Gal/Min

Contacts

Contact Type	Name	Title	Phone Numbers		Email Address
			Office	Emergency	
AC	GALE, DELRIE W		435-781-3365	435-789-8937	dgale@simplot.com

Service Connections

Connection Type	Meter Type Code	Meter Size	Number Connections
Residential	Metered	0	35
			35 Total Svc Connections

Storage

Total Storage: 240,000 GAL **Number of Units:** 3 **Adequate Capacity:** NO

No.	Name	Type	Effective Volume	Constr Matl	Overflow Elev	Activity Status	Press'd
ST003	2006 TANK	Ground	90,000 GAL	Concrete		A	NO
ST001	2000 TANK	Ground	60,000 GAL	Concrete		A	
ST002	2002 TANK	Ground	90,000 GAL	Concrete		A	

Distribution System

Pump Type	Total Dyn Head ft H2O P.S.I.	Pressure Adequate	Cross Connection	Auhority Statement
No				

Sources

No.	Source Name	Activity Status	Source Type	Well Dia.	Safe Yield *	Pump Capacity	Location Data On File	Water Type	Availability	Period of Operation	Grnd Wtr Indicator
WS001	WILDE SPRING	Active	SP				Yes	GW	Seasonal	5/1 to 9/30	

*Reports measured flow for wells, approved design capacity for all other sources.